

Cable Wiring Diagram for WXTrak in Parallel with KPC-3+ to Radio Transceiver

Jumper settings in KPC-3+:

J6 = center to 2: Puts power on KPC-3+ radio port connector to feed to WXTrak

J7 = center to 2: Puts power on KPC-3+ radio port connector to feed to WXTrak

J9 = NOR : Insures PTT output is truly an open drain output.

Software settings in KPC-3+:

CD = Software : Allows KPC-3+ to hold off transmit when XCD is present

KPC-3+ Radio Port
(DB-9M)

WXTrak Radio Port
(DB-9M)

Radio Connector
(DB-9F)

